

# 1101-1.29/1K

## BALL BEARING EXTRACTOR SET




in i-BOXX® 72

- > Ball bearing extractor set for more than 30 ball bearings
- > For removing ball bearings that are both on a shaft and in a housing
- > Non-destructive removal of deep-groove ball bearings without dismantling the shaft; no necessity to drill open the bearing cage (no chippings)
- > With Check-Tool insert for quick check of completeness
- > Insert for use in drawers with min. dimensions 340 x 260 x 60 mm
- > In GEDORE i-BOXX® 72 No. 1101 L
- > Dimensions: W 367 x D 316 x H 72 mm



1101-1.29/1K



1101 CT-1.29/1K



Contents	for ball bearing No.	kg	Code	No.
<b>2 Heads with spindle no. 1.29/1 + 1.29/3</b>	6000 6001 6002 6003 6004 6005 6006 6007	2.610	2963485	1101-1.29/1K
<b>5 Heads with spindle no. 1.29/10 - 1.29/35</b>	6008 6009 6010 6011 6012 6200 6201 6202			
<b>1 Handle no. 1.29/0</b>	6203 6204 6205 6206 6207 6300 6301 6302	1.750	2964414	1101 CT-1.29/1K
<b>2 Heads with spindle no. 1.29/1 + 1.29/3</b>	6303 6304 6305 6306 6307 6403 6404			
<b>5 Heads with spindle no. 1.29/10 - 1.29/35</b>				
<b>1 Handle no. 1.29/0</b>				

Description	kg	Code	No.
<b>Foam insert i-BOXX 72, empty</b>	0.110	2964449	EI-1101 CT-1.29/3K

# 1101-1.29/3K

## BALL BEARING EXTRACTOR SET



in i-BOXX® 72

- > Ball bearing extractor set for more than 40 ball bearings
- > For removing ball bearings that are both on a shaft and in a housing
- > Non-destructive removal of deep-groove ball bearings without dismantling the shaft; no necessity to drill open the bearing cage (no chippings)
- > With Check-Tool insert for quick check of completeness
- > Insert for use in drawers with min. dimensions 340 x 260 x 60 mm
- > In GEDORE i-BOXX® 72 No. 1101 L
- > Dimensions: W 367 x D 316 x H 72 mm



1101-1.29/3K



1101 CT-1.29/3K



Contents	for ball bearing No.	kg	Code	No.
<b>4 Heads with spindle no. 1.29/1 - 1.29/5</b>	6000 6001 6002 6003 6004 6005 6006 6007 6008 6009 6010 6011	5.780	2964392	1101-1.29/3K
<b>7 Heads with spindle no. 1.29/10 - 1.29/45</b>	6012 6200 6201 6202 6203 6204 6205 6206 6207 6208 6209 6210			
<b>1 Handle no. 1.29/0</b>	6211 6212 6213 6300 6301 6302 6303 6304 6305 6306 6307 6308	4.920	2964430	1101 CT-1.29/3K
<b>4 Heads with spindle no. 1.29/1 - 1.29/5</b>	6309 6310 6311 6403 6404 6405 6406 6407			
<b>7 Heads with spindle no. 1.29/10 - 1.29/45</b>				
<b>1 Handle no. 1.29/0</b>				

Description	kg	Code	No.
<b>Foam insert i-BOXX 72, empty</b>	0.110	2964449	EI-1101 CT-1.29/3K